




# P-305 PEDAL + CONNECTION BOX

# P-305 / PEDAL + CONNECTION BOX






The pedal P-305 has been created for those users that want to use the tool to place the electronic component in the correct position on the PCB, causing no thermal stress to the component until the solder joint is made.

# SETTING UP THE STATION

In order to make the tool not to heat the component until the pedal is pressed, the **Hibernation Delay** feature of the station has to be set to **0 min**. See the station manual for instructions on how to navigate through the Menu.


NOTE: Once in the main menu, if the pedal is already connected to the station, take the tool out of the stand and press and hold the pedal (if "Normally Open" mode is set) before entering the Tool Settings menu. Once in it, you can release the pedal.

## WORKING with "Normally Open" mode





Once in the correct position, **PRESS** and **HOLD** the pedal to make the solder joint.



### **TECHNICAL SPECIFICATIONS**

#### Pedal P-005

- Dimensions: 90 x 60 x 50 mm
- Cable length: 0.3 m
- Weight: 135 gr

#### **Connection Box**

- Dimensions: 102 x 198 x 45 mm
- Cable length: 0.3 m
- Weight: 385 gr.



This product should not be thrown in the garbage.



#### WARRANTY

JBC's 2 years warranty guarantees this equipment against all manufacturing defects, covering the replacement of defective parts and all necessary labour.

Warranty does not cover product wear due to use or mis-use.

In order for the warranty to be valid, equipment must be returned, postage paid, to the dealer where it was purchased enclosing this fully filled in, sheet.

SERIAL N°

STAMP OF DEALER

DATE OF PURCHASE

www.jbctools.com